



# Service Bulletin

**SP-028**

DATE: July 1, 2010  
TO: All Service and Parts Managers  
SUBJECT: Service Condenser Coils for Package Units

Due to Goodman no longer having the capability to manufacture older style 1.25" center condenser coils, the service replacement coils will be changing to the current style 1" center condenser coils.

In some instances, this will result in the service coil being a 1 (single) row coil versus a 2 (double) row coil and some coils will change from 3/8" to 5/16" tubing. In the case of the tubing size change on heat pump models, the defrost thermostat will have to be replaced. There is a new defrost thermostat for 5/16" tubing included with any service coil that requires a defrost thermostat change.

In some instances, these changes will result in a change to the total system refrigerant charge. In instances where there is a change to the total system refrigerant charge, there will be a label included with the new service coil that lists the updated required refrigerant charge. This label should be placed adjacent to the existing serial plate on the unit.

There may also be modifications to the existing tubing in order to complete the coil replacement. In these instances, the necessary tubing and instructions will be included with the service replacement coil.

Technical Services Department • 1810 Wilson Parkway • Fayetteville, TN 37334  
Main: 888.593.9988 • Service Fax: 713.316.5541