



# Service Bulletin

**SF-035**

DATE: July 9, 2010  
TO: All Service and Parts Managers  
SUBJECT: Emerson UltraCheck-EZ™ Motor Tester

We have received information from Emerson that some of the UltraCheck-EZ motor testing tools may have been improperly assembled and could result in unreliable operation. This tool was introduced 2/10/2010 for field testing the Emerson four wire motors used on our communicating furnaces and air handlers. The Goodman part is UTT-01.

Therefore we are requesting all UltraCheck-EZ motor testers be returned to Goodman. Please contact your CSR (Customer Service Representative) to request an RMA and credit for the returned testers. It will be necessary to reorder the UltraCheck-EZ motor testers to replenish your inventory.

Technical Services Department • 1810 Wilson Parkway • Fayetteville, TN 37334  
Main: 888.593.9988 • Service Fax: 713.316.5541